



**Product Name:** K-Router Plus

**Current Version:** S – 2.0.28.0

**Version Date:** February 2014

**Reference:** RD-001026

**Release Type:**

☐ Firmware ☒ Software ☐ Hardware ☐ New Product

**Technical Notes:**

- There is a known issue for K-Router+ when using infrared control in Protocol 3000 for specific machines

**Codependency with Other Products and Software:**

Product Name	Comments
VS-88HN, VS-48HN, VS-84HN, VS-66HN	
VS-88HDCPxI, VS-48HDCPxI, VS-84HDCPxI, VS-66HDCPxI	
VS-42HDCP, VS-42HN	
VS-44HDCP, VS-44HN	



KRAMER ELECTRONICS, Ltd.

E-mail: [info@kramerelectronics.com](mailto:info@kramerelectronics.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)



**Product Name:** K-Router Plus  
**Current Version:** S – 2.0.28.0  
**Version Date:** February 2014  
**Reference:** RD-001026

**Known Issues:**

- K-Router+ only works with Protocol 3000. IR control does not work on the codependent products when the product is set to Protocol 3000 or controlled by K-Router+. To control the product using IR, the product must set to Protocol 2000 and use the previous version of K-Router.

**Preceding Version:** S – N/A



KRAMER ELECTRONICS, Ltd.

E-mail: [info@kramerelect.com](mailto:info@kramerelect.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)