



Product Name: VP-747
Current Version: F – VSE 1.10, VSH 1.11
Version Date: February 2014
Reference: 6852

Release Type:

☒ Firmware ☐ Software ☐ Hardware ☐ New Product

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VP-747	Any	Yes	N/A

Technical Notes:

- An audio problem with Apple devices was fixed.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com



Product Name: VP-747
Current Version: F – VSE 1.10, VSH 1.11
Version Date: February 2014
Reference: 6852

The following changes were made in this version:

Fixes:

- There no audio on the output when Apple devices are connected to input.

Known Issues:

- There are no known issues.

Preceding Version: F – VSE 1.10, VSH 1.10



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com



Product Name: VP-747
Preceding Version: F – VSE 1.10, VSH 1.10
Version Date: July 2013
Reference: 6004

The following changes were made in this version:

Fixes:

- The device did not work properly in temperatures below 5°C.

Known Issues:

- There are no known issues.

Preceding Version: F – VSE 1.09, VSH 1.09



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com



Preceding Version: VSE 1.09, VSH 1.09
Version Date: February 2013
Reference: 5175

The following changes were made in this version:

Modifications:

- The HDMI EDID was modified to fix an audio problem with specific PCs:
 - Monitor Range Limits was removed from Detailed Timing #4.
 - VP-7xx was added to the Monitor Name descriptor.

Known Issues:

- There are no known issues.

Preceding Version: VSE 1.08, VSH 1.08



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com



Preceding Version: VSE 1.08, VSH 1.08

Version Date: January 2012

Reference: 2150

The following changes were made in this version:

Added Features:

- Polling input command support was added to get information about the input resolution using RS-232.

Known Issues:

- There are no known issues.

Preceding Version: VSE 1.07, VSH 1.07



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com



Current Version: VSE 1.07, VSH 1.07
Version Date: October 2011
Reference: 1157

The following changes were made in this version:

Added Features:

- A new command was added to the RS-232 protocol that emulates the T-BAR operation.

Known Issues:

- There are no known issues.

Preceding Version: VSE 1.06, VSH 1.06, VSK 2.11



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com



Preceding Version: VSE 1.06, VSH 1.06, VSK 2.11
Version Date: July 2011
Reference: 0109

The following changes were made in this version:

Added Features:

- The following broadcast resolutions were added:

720x480@59.94	1920x1080@23.98
1280x720@59.94	1920x1080@29.97
1920x1080i@59.94	1920x1080@59.94

- The T-Bar firmware version is visible when connected to the VP-747.
- A low latency mode option was added to the menu for CV input. It decreases the latency between the video input and output.

Known Issues:

- There are no known issues.

Preceding Version: VSE 1.05, VSH 1.05



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com



Preceding Version: VSE 1.05, VSH 1.05
Version Date: February 2011
Reference: 6580

The following changes were made in this version:

Fixes:

- The following error was fixed with Panasonic monitors: when turning the monitor OFF and ON, the HDCP communication between the monitor and VP-747 fails, resulting in no picture.

Known Issues:

- There are no known issues.

Preceding Version: Package 1.04, VSH1.04



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com



Preceding Version: Package 1.04, VSH1.04

Version Date: September 2010

Reference: 6392

The following changes were made in this version:

Added Features:

- Event mode ON - the LCM displays “Invalid operation” when any program button is pressed.

Fixes:

- HDCP handling fixed in the rare cases that HDCP handshaking failed that resulted in no picture being output.

Modifications:

- The aspect ratio default value was changed to Follow Output and Follow Output was enabled for any input output resolution.

Known Issues:

- There are no known issues.

Preceding Version: Package 1.02 (VSE1.02, VSI 2.07, VSD 11), VHS 1



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com