



**Current Firmware Version:** 5577  
**Version Date:** December 2011  
**Reference:** 1596

**Kramer Products Affected:**

Product Name	Minimum FW version for upgrade	Recommended for all units	Only if added features are required
VP-81K	Any	Yes	–

**Technical Notes:**

- This version fixes communication and IR control problems.

**Codependency with Other Products and Software:**

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: [info@kramerelect.com](mailto:info@kramerelect.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)



**Current Firmware Version:** 5577  
**Version Date:** December 2011  
**Reference:** 1596

The following changes were made in this version:

**Fixes:**

- Bugs in RS-232 / Ethernet protocol communication were fixed.
- Bugs in audio volume control via the RS-232 / Ethernet were fixed.
- An IR control problem was fixed: when the machine number of an IR command is different from unit machine number.

**Known Issues:**

- There are no known issues.

**Preceding Firmware Version:** N/A

