



Current Firmware Version: 1.3
Version Date: August 2012 (Update)
Reference: 3848

Kramer Products Affected:

Product Name	Minimum FW version for upgrade	Recommended for all units	Only if added features are required
VS-44HN	Any	Yes	–

Technical Notes:

- A preset numbering bug and an ALL OFF report in K-Router were fixed.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com



Current Firmware Version: 1.3
Version Date: August 2012 (Update)
Reference: 3848

The following changes were made in this version:

Fixes:

- The numbering of the setups under front panel buttons was in the wrong order.
- When one of the outputs was set off K-Router reported that all outputs were off.

Known Issues:

- The IR remote control does not work when the device is set to Protocol 3000. It does work when the device is set to Protocol 2000.

Preceding Firmware Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerelect.com

Web: www.kramerelectronics.com