



**Product Name:** MV-5  
**Current Version:** F – 1.0.0.8  
**Version Date:** July 2014  
**Reference:** 7469

**Release Type:**

☒ Firmware ☐ Software ☐ Hardware ☐ New Product

**Kramer Product Affected:**

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
MV-5	Any	Yes	N/A

**Technical Notes:**

- This release adds and fixes.

**Codependency with Other Products and Software:**

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: [info@kramerelectronics.com](mailto:info@kramerelectronics.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)



**Product Name:** MV-5  
**Current Version:** F – 1.0.0.8  
**Version Date:** July 2014  
**Reference:** 7469

The following changes were made in this version:

### Added Features:

- Disconnecting from the MV-5 is now indicated.
- A non-MV-5 device cannot be connected.
- Windows can be resized in any direction (left and top added).
- Windows can be positioned outside of visible area.

### Fixes:

- Output resolution window resizing was fixed.
- The Layer section was fixed.
- The aspect ratio section was fixed.
- The setup-store option was fixed.
- All parameters that were not synchronized with the device were fixed.
- Firmware upload via the application was fixed.
- Validation was added when the user enters an IP/Mask/Getaway address.
- Firmware limiting of windows width/height was added.



KRAMER ELECTRONICS, Ltd.

E-mail: [info@kramereel.com](mailto:info@kramereel.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)



### **Known Issues:**

- The MV-5 PC application does not display correctly on resolutions lower than 1024x768.
- Changing the screen resolution while the MV-5 PC application is open may result in improper display of the application. In this case shut down the unit and restart it.
- When cascading two units (output from one unit connected to an input of the other unit), the HDCP indication LED on the first unit may not display the correct information.

**Preceding Version:** N/A



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerelectronics.com](mailto:info@kramerelectronics.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)



**Product Name:** MV-5  
**Current Version:** NP – 1.0  
**Version Date:** May 2014  
**Reference:** 4400

This is a release note for a new product.

**Known Issues:**

- The MV-5 PC application does not display correctly on resolutions lower than 1024x768.
- Changing the screen resolution while the MV-5 PC application is open may result in improper display of the application. In this case shut down the unit and restart it.
- It is not possible to install the MV-5 PC application and the MV-6 PC application on the same system.
- When cascading two units (output from one unit connected to an input of the other unit), the HDCP indication LED on the first unit may not display the correct information.

**Preceding Version:** N/A



KRAMER ELECTRONICS, Ltd.

E-mail: [info@kramereel.com](mailto:info@kramereel.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)