



Product Name: VS-88H
Current Version: F – 1.2
Version Date: May 2016
Reference: 10490

Release Type:

☒ Firmware ☐ Software ☐ Hardware ☐ New Product

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VS-88H	Any	Yes	N/A

Technical Notes:

- An EDID corruption problem was fixed.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: VS-88H
Current Version: F – 1.2
Version Date: May 2016
Reference: 10490

The following changes were made in this version:

Fixes:

- After copying an EDID and performing a factory reset, the EDID was corrupted.

Known Issues:

- There are no known issues.

Preceding Version: 1.1



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerelectronics.com

Web: www.kramerelectronics.com



Product Name: VS-88H
Preceding Version: 1.1
Version Date: June 2012
Reference: 3124

The following changes were made in this version:

Fixes:

- Allows passing of information packages in 3D signals that are required by some 3D screens.

Known Issues:

- There are no known issues.

Preceding Firmware Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerelectronics.com

Web: www.kramerelectronics.com