



**Product Name:** VS-84HDCPxI

**Current Version:** F – 1.2

**Version Date:** May 2016

**Reference:** 10490

**Release Type:**

☒ Firmware ☐ Software ☐ Hardware ☐ New Product

**Kramer Product Affected:**

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VS-84HDCPxI	Any	Yes	N/A

**Technical Notes:**

- An EDID corruption problem was fixed.

**Codependency with Other Products and Software:**

- There is no codependency with other products or software.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerel.com](mailto:info@kramerel.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)



**Product Name:** VS-84HDCPxI  
**Current Version:** F – 1.2  
**Version Date:** May 2016  
**Reference:** 10490

The following changes were made in this version:

**Fixes:**

- After copying an EDID and performing a factory reset, the EDID was corrupted.

**Known Issues:**

- There are no known issues.

**Preceding Version:** N/A



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerelectronics.com](mailto:info@kramerelectronics.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)